


# NYB LEFKAS OFFICE

OFFICES THROUGHOUT THE UK AND EUROPE



Year:

Location:

LOA:

Beam:

**Draft:** 

Remarks:

This Jeanns genera\*

. UK+ 44 203 051 0525 / Mob.+306945347870

Kyachtbrokers.com | over 700 boats listed

REF: 22369





# Mechanical and Rigging

### CONSTRUCTION

GRP hull

Balsa cored deck

Iron keel (partially lifting).

Masthead sloop

### **SAILS**

Main sail 17.6m

Genoa 34 m

Storm sail 4.8 m

Cruising chute 72.3 m

Slab reefed main

Roller furling genoa

#### **ENGINE**

Yanmar 2 GM20 twin cylinder diesel 18 hp

Shaft drive

3 blade fixed propellor

Engine last serviced 2016

### **ELECTRONICS**

**GPS** 

Radar

AIS

Auto pilot

VHF radio

Depth sounder

Log/speed

Wind instrument

Wind indicator at mast head

**Navtex** 

Most electronics 3 years old.

## **ELECTRICAL**

Domestic batteries x 2

Engine start battery x1

Windless battery x1

Shore power

# Inventory

### **SAFETY**

Life raft

Life buoy

Life jackets

Danbouy

Flares

Fog horn search light radar reflector Fire extinguisher Fire blanket Bilge pump manual x1 Bilge pump electric x1

DECK
Boarding ladder
Spray hood
Sail cover
Warps x8
Fender x8
Cockpit cushions

Outboard motor Mariner 2 hp (10 years old)

Wind generator

# Accommodation

ACCOMMODATION
4 berths in 2 cabins
1.8 meter headroom
Chart table
Saloon table
Hanging locker
Oven
Stainless sink
Refrigerator
pressurised water system
Stereo
DVD player

# Remarks:

This **Jeanneau Attalia** is ready for sea with recently upgraded electronics, boom brake, solar panels and wind generator. A very tidy live aboard or holiday cruiser at a very attractive price.

Contact: Network Yacht Brokers Lefkas Cleopatra Marina (Dock side) Aktio-Preveza Ionian Islands, Greece. **Tel:** UK+ 44 203 051 0525 / Mob.+306945347870 Email: info@nyblefkas.com Disclaimer: Ionian Yacht Sales Ltd t/a Network Yacht Brokers Lefkas offers the details of this vessel for sale but cannot guarantee or warrant the accur of the information contained in the specification or warrant the condition of the vessel or equipment. A buyer should instruct his agents, or surveyors, to