

EAST ANGLIA OFFICE

OFFICES THROUGHOUT THE UK AND EUROPE



Year:

Location:

LOA:

Beam:

Draft:

Remarks:

New to the engines $H\nu$

s powered by two Volvo TAMD41 ruising speed approx 22knots. "Bounty a generous cockpit for entertaining and s including engine servicing (May 2021) New


ryachtsales.com **T:** +44 (0)1255 672500

Kyachtbrokers.com | over 700 boats listed

REF: 484

aling





Mechanical and Rigging

Date of last engine service 01/05/2021

Full service: water pumps rebuilt, oil, belts, impellers changed.

New propellers (2021)

2 x Fuel Tanks

Inventory

Depthsounder - Raymarine

Log-Speedometer - Raymarine

Navigation Centre - Raymarine

Plotter - Raymarine ES Series

Autopilot - it's all connected but needs wiring up and fixing

Compass

GPS - Raymarine ES Series

VHF

Radar - Raymarine ES Series

Search light

Anchor light

Anchor

SeaSafe Pro life Life Raft - 6 person

Swim Platform

Shore power inlet

2000 watt Inverter

2 x engine batteries

2 x 240 amp leisure batteries (2021)

Victron Battery Charger

Manual Bilge Pump

Electric Bilge Pump

Cockpit Speakers

Cockpit Cover

Trim Tabs

Seating Capacity 8

Antifouled April 2021

New Anodes April 2021

Accommodation

1 x Double (V) Berth

6kW Diesel heater

Blowers

Pump marine head

Gas hob

New Dometic 12v fridge

Complete rewire inside with new controls and switches

New cabin lights

Hot Water pump (new)

Shower pump (new)

TV

Radio

CD player 240v sockets

Remarks:

New to the market Sea Ray 310 Express Cruiser. Built in 1992. "Bounty Hunter" is powered by two Volvo TAMD41 engines providing 200HP each on shaft drives. Max speed approx 28knots, cruising speed approx 22knots.

"Bounty Hunter" also features an extended aft platform, cockpit enclosure, and has a generous cockpit for entertaining and accommodation below.

Much work has been completed in recent times including engine servicing (May 2021) New batteries, new Victron charger/inverter, rewired, new clarifier, new Raymarine plotter etc, approximately £10,000 worth of work. However it is fair to say this boat still requires some work mostly of a cosmetic enhancement to the interior to fully bring this boat up to top condition. The owner advises, this boat is mechanically sound and reliable, just needs some work to complete. The owner is selling as he wishes a larger boat for his family.

Contact: Network Yacht Brokers East Anglia Titchmarsh Marina, Coles Lane, Walton-on-the-Naze, Essex CO14 8SL

Tel: +44 (0)1255 672500

Email: sales@westwateryachtsales.com